



1999 Challenger 604

Serial Number **5400**

Registration **N60055**

Airframe

4,786 Hours
2,443 Cycles

Engines

GE CF34-3B
#1 4,634 Hours 2,347 Cycles
#2 4,786 Hours 2,443 Cycles

APU: GTCP 36-150

3,877 Hours Since New

Key Features

Bombardier Smart Parts Plus
GE On-Point Engine Coverage
APU on Honeywell MSP Gold

192 Airframe/Gear Restoration June 2015
Duncan-Lincoln

Avionics/Options

Collins Pro Line 4 Avionics System
Collins TTR-2100 TCAS w/change 7.1
Dual Collins FMS-6000 FMS's w/WAAS LPV
Dual Collins GPS-4000S
Six Collins EFIS EFD-4077 Displays
Dual Collins VHF-422C Comms w/8.33 Spacing
Dual Collins TDR-94D Mode S Transponders
Collins RTA-854 Color Weather Radar
Honeywell Mark V EGPWS w/Windshear
Collins HF-9000 HF Comms w/SELCAL
Dual Collins FCC-4000 Autopilot
Triple LTN-101 IRS's
Dual Collins VIR 432 Navs
Dual Collins ADF 462 ADFs
Collins DBU-5000
Dual Collins DME-4000 DME's
Dual Collins ALT-55B Radio Altimeter

Precision Plus Upgrade
DAC International Class III EFB's
XM Weather with Graphic Nexrad Radar
Collins 906 SATCOM
Metric Altitude switch
Artex 406 Mhz ELT
Common Keyed Locks
Airshow 400 Flight Information System
Aux input for Movie server system
Blu-Ray Disc DVD Player
Multi-Disc CD Player
24" HD Monitor on forward LH bulkhead
26" HD Monitor on the aft RH bulkhead
Convection Oven
Microwave Oven
Two Over Water Life Rafts with 406 Mhz ELT's
Universal CVR 120 Cockpit Voice Recorder Honeywell AFIS

Interior

Floor plan configured for nine (9) passengers plus a forward jump seat. Featuring a forward four (4) place club with a fully berthable three (3) place divan and two (2) place club aft. The individual seats are fully articulating and completed in a light cream leather with Pininfarina Design insets accented by coordinating Earthtone carpeting and side panels. High gloss burl veneer cabinetry is found throughout the cabin.

Exterior

Overall White with Blue and Silver Accent Striping

SPECIFICATIONS SUBJECT TO VERIFICATION UPON INSPECTION